

Version 13

Update news



Version 13 is another product upgrade packed with new features driven by your requests and user feedback.

Please keep the ideas coming—we're always happy to learn new ways our products can help you. Email your ideas, feedback and requests for improvements to support@mpanel.com

Corner Fittings




Corner hardware such as "D-Rings" are now included in the pattern output plot file accurately locating the fitting base so there is no need to measure offsets.

Corner Styles




New Truncated and Rebated corner styles added to plotter output



Seam match marks




Match marks added to seams ensure accuracy during fabrication



Shaped Seam - max dip offset



Shapes with large height differences produce seams with non-central max dips — V13 now identifies the location and size of max seam dip.



Panel Mapping

Now shows total length of fabric required to fabricate the sail.

We trust you will enjoy these new features and that they will benefit your company. Thank you for your continued support and we again, encourage you to provide feedback and suggestions for improvements.

MPanel Support Team